

goot TIP THERMOMETER TM-100



OPERATION MANUAL

Thank you for buying **goot** Tip Thermometer TM-100. Read this Owner's Operation Manual before using your tip thermometer.

SAFETY MARK DEFINITIONS

In this manual, the following safety marks are used.



Careless handling may result in injury to yourself or to others, physical damage, or a system failure of this device.



NOTE A note or word of advice.

TAIYO ELECTRIC IND.CO.,LTD.


www.goot.co.jp E-mail: info@goot.co.jp

KEEP THIS MANUAL FOR FUTURE REFERENCE

3. HOW TO ATTACH / DETACH THE SENSOR


HOW TO ATTACH

1. Attach the red sheath side of the sensor to the connecting pin on the red silicon plate of the device.



HOW TO DETACH THE SENSOR

Hold the device firmly and turn it upside-down. Press the left button several times, then the sensor will detach.



Attach with correct orientation, and right side up. Incorrect attaching will cause wrong temperature data. Put the sensor on the connector pin firmly. To avoid damaging the sensor, do not bend or deform it.



When using the Sensor-life Counter function (described later), reset the sensor-damage value in measuring mode after replacing with a new sensor.

4. HOW TO MEASURE THE TEMPERATURE

1. Press **POWER** to display the set-unit **88.8** Celsius or **88.8** Fahrenheit. When the room temperature appears the device is ready for measurement. (measuring mode)
2. Put the tip to the sensor chip, applying fresh solder to both parts. Please read when the displayed temperature is stable.



CAUTION Too much pressure to the sensor risks damage. Apply the tip on the chip gently.



NOTE Be sure to attach the sensor properly before starting measurement. When the alarm (shown left) appears, it means that the sensor is not attached properly or measured tip's temperature is out of range. Check for a break in the sensor, or check the settings of the device.

TABLE OF CONTENTS

1. SPECIFICATIONS
2. PACKAGE CONTENTS / NAMES OF PARTS
3. HOW TO ATTACH / DETACH THE SENSOR
4. HOW TO MEASURE THE TEMPERATURE
5. FUNCTION AND SETTING
6. REPLACEMENT PARTS / OPTION
7. OPERATIONS

1. SPECIFICATIONS

UNIT

MODEL	TM-100
Power Supply	AA battery LR6 x 4pcs: 6V
Dimension	83(W) × 140(H) × 38(D)mm
Weight	150g (w/o battery)
Temperature Resolutions	1°C
Ranges	w/sensor (TM-100S): 0-550°C(32-932°F) w/optional probe (TM-100SP): 0-700°C(32-1292°F)
Accuracy	± 0.5% of the full scale (w/o sensor error)
Display	LED indication
Operating Environment	0-50°C, 20-85%RH (no condensation)

*Over 1000°F, temperature is indicated by F-1 and the last three digits of degrees °F.

SENSOR

Model	TM-100S
Sensor Type	Type K (CA type)
Size	9(W) × 45(H) × 3(D)mm
Weight	0.8g

CALIBRATION

Accuracy assured for 1 year from the day of purchase. After 1 year we also offer calibration for a fee. Please contact your nearest distributor.



CAUTION

1. The measuring tip is very hot. Handle with care. Careless handling may result in fire or personal injury.
2. Be sure not to heat the plastic case such as by contact with the hot tip, except to the sensor, or by blowing warm air onto the body. Excess heat will melt or damage the case.
3. Do not open the device. Sensitive parts might be damaged.
4. The LED can flash even when power is off. This is not a system error. This is an effect of static electricity.
5. Avoid impacts to prevent damage to, or deterioration of, the product during transportation. Be especially careful to avoid deformation or breakage from dropping.



NOTE The sensor and the batteries are consumable items.

Printed in Japan, NOVEMBER 2012



NOTE Flux residue on the sensor chip, or a stained tip will reduce the accuracy of the measuring sensor. Clean them regularly with CP series (solder wick). Too little solder on the chip may result in wrong measuring data. Use the proper solder amount for your tip size.



NOTE The sensor reception will become worse because of the degradation of the chip after repeated use. Replace the degraded sensor with a new one to ensure accurate measuring. Please use the below Sensor-Alarm Function for replacement timing.

5. FUNCTION AND SETTING Please refer to [7. OPERATIONS] for each function.

A. Measuring Mode

After power-on, always start with the measuring mode. Measuring mode has the following functions. (Digit change/setting can be configured in setting mode.)

Peak-Hold Function (factory default setting: OFF)

In measuring mode, press the **PEAK HOLD/MODE SET** button, then the HOLD ON lamp **6** will light up. Retains display of peak temperature. Press the **PEAK HOLD/MODE SET** button again to unset the peak hold function.

Automatic Power-Off function (factory default setting: 60 seconds)

The device will power off automatically when 100°C or lower is continuously measured for more than the preset time. The setting time for the Auto Power-Off can be changed in units of 30 seconds. (MAX 300 seconds) When the displayed temperature is under 100°C in measuring mode, the count time will be reset as the result of pressing **▲SENSOR RESET** button within the preset time. And extend the time until Auto Power-Off.

Sensor-Life Counter Alarm (PAT.P) (factory default setting: 200 times)

Weigh and integrate the sensor damage by our own calculational procedure by counting in units of 3-seconds' use at temperature 350°C(662°F). The alarm lamp **6** will flash when the counter exceeds the set number of counts, to indicate the approx. replacement-timing of the sensor. To turn off this function, set the preset value at 0.

To reset (return to 0) the integrated value of the damage, press and hold the **▲SENSOR RESET** for over 3 seconds in measuring mode.

Battery Alarm

The battery lamp will flash when the battery voltage drops lower than specified value to indicate the approx. replacement-timing of the battery.




NOTE The sensor life "200 times when counted in units of 3-seconds" use at temperature 350°C(662°F)." is just a tentative indication. The actual sensor-life can be changed by your operating conditions. When replacing the sensor, reset the damaged value. Figure out the sensor life and change its set value for effective use.

B. Setting Mode

To enter setting mode, press and hold the **PEAK HOLD/MODE SET** button for over 3 seconds in measuring mode. In setting mode, every pressing of the **PEAK HOLD/MODE SET** button will shift the set-


2. PACKAGE CONTENTS / NAMES OF PARTS

■ **UNIT** Protective clear seals on the key panel & silver plate.



The enclosed batteries are for testing only.

FRONT PANEL



ting function. To change the setting value, press the **▲SENSOR RESET** button. To return to measuring mode, press and hold the **PEAK HOLD/MODE SET** button for over 3 seconds in setting mode.



NOTE To turn off the device, return to measuring mode. In setting mode, the power off (& Auto Power-Off) function does not work.


6. REPLACEMENT PARTS / OPTION

■ Sensor (3pcs)

TM-100S

■ Sensor Probe (for solder pot)

TM-100SP



7. OPERATIONS

A. Measuring Mode

After power-on, always start with the measuring mode.

PEAK HOLD ON/OFF	Extension of Automatic Power-Off time	Sensor Damage Reset (Return to 0)
Press the PEAK HOLD/MODE SET	Press the SENSOR RESET	Press and hold the SENSOR RESET over 3 seconds.

B. Setting Mode

To switch between setting/measuring mode, press and hold **PEAK HOLD/MODE SET** for over 3 seconds.

Key Operation	Turn	Display	Function & Range
Shift	↓	88.8	Set the time (seconds) until Auto-Power OFF. Ranges: 0-300 (in units of 30seconds) Default setting: 60s. Turns off at 0.
Press the PEAK HOLD/MODE SET	↓	88.8	Set the temperature display in Celsius (°C) or Fahrenheit (°F). The setting °C or °F Lights up. Default setting: °C.
Setting value change	↓	88.8	Set the sensor-life value. Ranges: 0-500 (in units of 50 times) Default setting: 200 times. Turns off at 0.
Press the SENSOR RESET	↓	88.8	Display the sensor-damage value. Resetting displays 0. Default setting 0.
	Return to start	88.8	